## GENERAL PLASTICS MANUFACTURING COMPANY



PLANT: 4910 Burlington Way (206) 473-5000

### P.O. BOX 9097 TACOMA, WASHINGTON 98409

October 20, 1983

TOLL FREE Seattle-Renton Area (206) 623-2795

U. S. Environmental Protection Agency 1200 Sixth Avenue Seattle, Washington 98101

Attention: Mr. Danforth Bodien

Toxic Substances Control Branch

M/S 524

Reference: Your letter of October 6, 1983 regarding Western Processing Co., Inc.

Gentlemen:

Enclosed is information regarding material which General Plastics sent to Western Processing Company, Inc. for disposal.

The material sent was a Fremont "Free-off" 550, Cold Stripper, manufactured by Fremont Industries, Inc. in Shakopee, Minnesota. One drum containing approximately 250 lbs. of this chemical was shipped to Western Processing on January 16, 1980, via Pozzi Brothers Transportation, Inc. We have enclosed a bulletin and material safety data sheet on the Fremont 550 Stripper, along with a copy of the Pozzi Brothers bill of lading for your information.

We sent this Fremont 550 stripper to Western Processing with an order and understanding that they would see to its' proper and safe disposal which fulfills General Plastics legal responsibilities.

This information should allow you to resolve this matter with Western Processing.

Sincerely,

GENERAL PLASTICS MANUFACTURING COMPANY

Henry T. Schatz,

-President

COMPLIANCE BRANCH EPA - REGION X

MANUFACTURERS OF PLASTIC FOAM, PLASTIC COATINGS, PLASTIC TREATMENTS

HTS/jp


Enclosures

FABRICATORS OF PLASTIC SHEETS INTO AIRCRAFT. ATOMIC ENERGY, INDUSTRIAL AND COMMERCIAL ITEMS

SUPPLIERS OF PLASTIC MATERIAL OF ALL KINDS


## B) ULLETIN

## FREMONT "Free-Off-550"



NOZZLE





Clean hot melt residue & char from nozzles & melt tanks, quickly and completely with "Free-Off" 550 Cold Stripper.

### FEATURES

- Cold Stripper Easy to use
- Cleans residue completely
- Non-flammable
- . Economical low rate of evaporation
- . Use at room temperature no heating
- . High strength
- . No mixing or diluting
  - Rinse clean with tap water
- . Use during normal downtime
  - Does not harm normal metals of construction

Fremont "Free-Off" 550 Stripper is available in:

55 gal. drum 15 gal. drum

This powerful stripper designed to effectively remove all hot melt residue and char from pozzles and melt tanks.

in inell does not dissolve in "Free-Off" 550, allowing use of the stripper many times

350-78 B

**OVER** 

Refer to manufacturer's manual for instructions to dismantle nozzle and meli rank.

Place "Free-Off" 550 in a container large enough to allow PARTS TO BE COMPLETELY IMMERATE. Avoid placing hot components in the solution. Do not heat stripper. Product is preferably used stainless steel (316 ss) tank, aluminum 3003 series H-14 temper (.100 thickness), or polyethylene lined tanks. It is commonly used a cold rolled steel tanks, however there may be deterioration of this type tank over a long duration of time. Product should not be used in any type of galvanized or rubber-lined tank. The use of Fremont 550 in any other tank construction material should be serified with Fremont Technical Representative. NOTE: Container with a cover is preferred to minimize vapor loss.

Submarge nozzle and melt tank in "Free-Off" 550 long enough (3-24 hours) to loosen hot melt esidue

Remove parts from tank and flush completely with water.

Any residue left can be easily removed with a stiff bristle brush

Wash parts clean with water and dry.

### **PLEASE NOTE**

I melt tank is not removable from the unit, contact manufacturer of the equipment to determine effect of "Free-Off" 550 on check valves, pumps, seals, and other possible susceptible components.

CAUTION: Contains cresylic acid, formic acid. Irritating to skin and respiratory tract. Direct contact can cause severe eye and skin injury. Overexposure to vapors can cause headache, dizziness and nausea.

5AFETY AND FIRST AID: Keep container closed when not in use. Keep out of reach of children. Do not take internally. For skin and eye contact, flush immediately with plenty of water for 15 minutes and call physician immediately. For inhalation exposure, take to fresh air.

PRECAUTIONS: When handling or working with product wear all protective equipment: chemical esistant (Neoprene) gloves, rubber apron, rubber boots, face shield or safety goggles. Use only with adequate ventilation. For respiratory protection use NIOSH approved respirator for organic vapors and acid gases. Do not store or use near open flames, electrical arc, or heat.

### **EXTENT OF WARRANTY**

mportant Notice to Purchaser (anti/or User). Fremont makes no warranty of any kind, expressed or implied, except that the materials sold hereunder shall be of Fremont's standard quality, and Buyer assumes all risk and liability whatsoever, resulting from the use of such materials whether used singly or in combination with other substances. This product is NOT for home use—it is for Industrial use only!

this product is <u>not</u> to be repackaged for resale without the expressed knowledge and written permission of the manufacturer and without proper and approved warning statements.

## U.S. DEPARTMENT OF LABOR

Occupational Safety and Health Administration

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

FLAGT	s ma
	- · · · · · · · · · · · · · · · · · · ·

OMB No. 44-RI38

SEC	CTION I
FREMONT INDUSTRIES, INC.	EMERGENCY TELEP NE NO. (612) 445-4121
ADDRESS / Vumber, Street, City, State, and ZIP Code: P.O. BOX 67, Valley Industrial CHEMICAL NAME AND SYNONYMS	Park, Shakopee, MN 55379  TRADE NAME AND SYNONYMS FREMONT 550 Cold Stripper
Solvent - Acid	Compounded
SECTION II - HAZA	ARDOUS INGREDIENTS
TLV	TLV

PAINTS, PRESERVAT	IVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	NA			BASE METAL NA		
CATALYST	. NA			ALLOYS NA		
VEHICLE	NA			METALLIC COATINGS NA		
SOLVENTS	NANA			FILLER METAL PLUS COATING OR CORE FLUX NA		
ADDITIVES	NA		ļ 	OTHERS		
OTHERS	•					
н	AZARDOUS MIXTUR	S OF (	OTHER LI	OUIDS, SOLIDS, OR GASES	%	TLV (Units)
	Cres	vlic	acid			5 pp
	Form	ic A	\cid			5 pp

SECTION III - PHYSICAL DATA .					
BOILING POINT (°F.)	104	SPECIFIC GRAVITY (H20-1)	1.235		
VAPOR PRESSURE (mm Hg.)	Unknown	PERCENT, VOLATILE BY VOLUME (%)	70.0		
VAPOR DENSITY (AIR=1)	Unknown	EVAPORATION RATE	Unknown		
SOLUBILITY IN WATER		forms an emulsion.			

SEC	CTION IV - FIRE A	ND EXPLOSION HAZARD DATA	
FLASH POINT (Method used)	NA	Unknown for mixture Lei	Uel
EXTINGUISHING MEDIA	NA NA		
SPECIAL FIRE FIGHTING PROC	EDURES NA		
,			
UNUSUAL FIRE AND EXPLOSIO	ON HAZARDS Produc	ct contains Methylene Chloride	- Will
form explosive	mixture in at	mosphere of high oxygen conten	t.

,	S	ECTION V	/ - HEA	LTH HAZARD DATA
THRESHOLD LIMIT	VALUE	<del></del>		
''114746767	rofuskin a	nd resp	irator	ry tract. Loss of consciousness.
Direct cor	ntact can c	ause se	vere e	eye and skin injury. Nausea & dizzines
EMERGENCY AND F	FIRST AID PROCED	JRES Inh	alatio	on: Take to fresh air.
Skin: Flus	sh immediat	ely wit	h wate	er. Contact physician.
Eyes: Flu	sh with wa	ter imm	ediate	ely, continue for 15 min. Contact
physician	immediatel	у		
		SECTION	IVI - R	EACTIVITY DATA
STABILITY	UNSTABLE		CONDITION	NS TO AVOID
	STABLE	Х		
AVOID CONT	Materials (4 anoid) act with s	trong c	xidizi	ing agents - strong alkalies.
HAZARBOUS DESCRI	YEXTAE" BHAY	or carl	on die	oxide, phosgene and hydrogen cloride.
HAZARDOUS MAY OCCUR CONDITIONS TO AVOID			CONDITIONS TO AVOID	
POLYMERIZATION	WILL NOT	WILL NOT, OCCUR		
			•	

# SECTION VII - SPILL OR LEAK PROCEDURES STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Wear all protective equipment when cleaning up spills or leaks. Remove all sources of open flames, sparks or heat. Avoid breathing vapors. Dike and pump into suitable container. Dry mop or use absorbant to pick up remainder. Place into suitable waste container. WASTE DISPOSAL METHOD Dispose of in accordance with local, state or federal regulations. Do not flush into municipal sewer system. Product contains phenol.

	SECTION VIII - SPECIAL I	PROTECTION	INFORMATION	
NIOSH ap	ROTECTION (Specify type) proved respirator for or	ganic vapo	ors and acid gases.	
VENTILATION	LOCAL EXHAUST		SPECIAL	
			OTHER	
PROTECTIVE GLI Chemical	resistant (neoprene).	EYE PROTECTI	ONFace shield or safety goggle	
OTHER PROTECT Apron -	DOOTS (Chemical resistar	it).		

## SECTION IX SPECIAL PRECAUTIONS PRECAUTIONS PRECAUTIONS PRECAUTIONS PRECAUTIONS Covered when not in use. Do not store, or use near open flames, OTHER PRECAUTIONS Azardous decomposition products. Do not get into eyes or on skin. Do not take internally. Can cause severe burns to body tissues. PAGE (2) Eye wash and safety shower should be provided. Form OSHA-20 Rev. May 72

	S S S S S S S S S S S S S S S S S S S	The same	
our S Aug	Section of the state of the sta	i i	
must by lamage report	Sifical Barriers	-	
made and/or ed in u	that the that the that the that the that the that the the the the the the the the the th		
in writing while	A G		
secovers to Form	NO STATE OF THE PARTY OF THE PA		
Forward by the Parties	17. Tell (18. 18. 18. 18. 18. 18. 18. 18. 18. 18.		
toger Williams and	NOO STEEL		
the day	2 6 5 5 2 5 5 5		
by the	8		
Parties	The state of the s		
13/20 000	13		
the de la	Tan .		
of Contact him or on rent good on the date here	THE PERSON NAMED IN COLUMN TO SERVICE AND		
of Contact, which he date hereof which here date hereof which	A STATE OF THE STA		
Carrier Carrier of which as	POZZI BROS	TR ANSPORT	TATION INC
warder that clamage and/or loss discovered by the consignee after the parties hereof which the consignee after the carrier to which so the classifications and the classes the parties hereof the parties hereof which the consignee after the cate hereof which the cate hereof which the consignee after the cate hereof which the c	POZZI BROS.  SEATILE 872-3570  The suppression of the property order in contents of pooling to the property order in contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the contents and pooling to the property order in the	TRANSPORT	TATION INC. TACOMA 924-0400

3623

CONSIGNED TO	(Mail or street address of consign	ee-For purposes o	f notification	only.	)	SHIPPER'S NO.		
	Western Processing Company, Inc.							
DESTINATION STREET CITY & STAT	7215 South 196th		,		ADVANCE	C.O.D.		
ROUTE:	POZZI BROS					AMT.\$		
No. Pkgs.	Kind of Package, Description of Articles, Special Marks, and Exceptions	(Sub. to Corr.)	Class or Rate	1	CHARGES	C.O.D. charge   Shipper		
1 dr	um Chemicals NOI	(500. 10 0011.)	0			to be paid by \ Consignee \		
	Caution: Corrasive Material	285#				Subject to Section 7 of conditions of applicable bill of lading, if this shipment is to be delivered to the consignee without recourse on the consignor, the consignor shall sign the following statement:  The carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.		
	our # 7837 CR 538							
						Per		
	FREIGHT PREPAID					If charges are to be prepaid, write or stamp here, "To be Prepaid."		
SHIPPER			-			TOTAL AMOUNT		
JAHARA	GENERAL PLASTICS MFG. CO.		- 1	1		COLLECT \$		
STREET & CITY	3481 South 35th Street	( Der	57 8	hi		TOTAL AMOUNT PREPAY \$		
"If the shine	Tacoma, Washington 98409	the bill of lading	shall state w	hether	it is "carrier's o	r shipper's weight."		